

Vālodzes Assessed receiver levels Esosa situacija S

2

Receiver	Dir	X	Y	Z	GH	Ld	Ld,diff
		m	m	m	m	dB(A)	dB
Alksnīši	W	595318,26	355379,11	148,52	140,52	36	---
Baloži	W	595296,54	355295,81	148,41	140,41	38	---
Birztales	S	594819,75	355692,20	161,77	153,77	39	---
Dzērves	NE	593397,53	355085,18	143,66	135,66	47	---
Jaunpāvuli	SE	593739,14	356286,50	136,82	128,82	38	---
Kalna Upmaži	NW	595464,69	354623,93	149,46	141,46	37	---
Krūmkalni	S	594850,59	355391,06	169,91	161,91	41	---
Kurmi	SE	593749,75	356320,69	135,21	127,21	37	---
Mazstrīķeži 1	SE	593458,54	355314,08	143,90	135,90	55	---
Norišas	SW	595152,16	355770,13	147,49	139,49	38	---
Norkalni	NE	593106,55	355526,23	129,69	121,69	43	---
Saulītes	NW	595077,68	354574,17	164,26	156,26	34	---
Silnieki	NW	595020,82	354763,46	162,28	154,28	37	---
Strikeli	N	593326,31	355249,18	136,95	132,95	61	---
Vecpāvuli	SW	593725,65	356244,78	135,51	127,51	38	---
Zvirgzdiņi	SW	594933,10	356011,75	144,61	136,61	47	---

Vides eksperti, Ganību dambis 24D-25, LV-1005 Rīga, Latvia

1